

**Office of The Executive Engineer
Construction Division-1, P.W.D., Aligarh**

(Email ID- cd1pwdaligarh@yahoo.in)

Ref. No.

25 / 9c

Date : 14.09.2022

BUILDING SAFETY CERTIFICATE

TO WHOM SO EVER IT MAY CONCERN

This is to certify that I have inspected the Dharam Samaj Bal Mandir Senior Secondary School building on request of Mr. Sanjay Kumar Goyal (Manager) at Parao Dubey, Aligarh. I found the following observations,

1. Present Position of the School Building is satisfactory.
2. Drinking water facility is available in the school campus which is supplied Through submersible pump.
3. School building is situated on the link Road of Parao Dubey, Aligarh i.e. building approach is satisfactory.

In my opinion the structure of the school building is constructed as per National Building Code-2005 & the present condition of the building is satisfactory but regular maintenance of the building is must.




Assistant Engineer

C.D.-1, P.W.D.,

सहायक अभियंता
नि० वि० निकास वि० नि० वि०
Aligarh


महलीगढ़


Principal
Dharam Samaj Bal Mandir
Sr. Sec. School Parao Dubey, Aligarh



Manager
Dharam Samaj Bal Mandir
Sr. Sec. School, Aligarh